

H

G

F





E

D

C

B

A



Note:

RCD: STD: Key Dimension:*

1 RCD: Required Control Dimension ,These Dimensions need Process control & capability(initial and ongoing), 100%inspection, poke yoke, etc.as appropriate.

2 STD: Statistically Toleranced Dimension ,These Dimensions need demonstration of ongoing process capability (Cp/PpK).

3 Key Dimension : These Dimensions are defined by ME/Mfg , and need inspection as appropriate.

If you want more information , please review the criterions of 《TC-RDW-18》 and 《TC-QAW-40》

TITLE	Antares 1K/1.5K EBM OUTLINE DRAWING	DRAW	NICOLE SUN 2016-07-26
PART NO.	F9000-001860-00P	DESIGN	NICOLE SUN 2016-07-26
MATERIAL	SEE NOTES	CHECKED	
COATING	SEE NOTES	SAFETY	RACHELL YUAN 2016-07-26
UNITS	mm	APPROVED	BENNETT FEI 2016-07-26
SHEET	1/1	 A3 SCALE 1:1 E.T.N ELECTRICAL SECTOR	